



U.S. Department of Labor
Mine Safety and Health Administration



HAULAGE SAFETY



BEST PRACTICES

1. Provide and maintain adequate berms or bumper blocks at all dumping locations.
2. Examine dumping locations for hazards prior to commencing work.
3. Utilize a bulldozer with the "dump-short, push-over" method of spoiling material.
4. If dumping over a berm, back perpendicularly or at a slight angle, so that the driver side wheels contact the berm first.
5. Slope the dump area so that trucks must back up a slight grade.
6. Ensure that drivers are trained to recognize and avoid dumping hazards.
7. All personnel, who operate or ride in mobile equipment, should wear seat belts at all times the equipment is in motion.



U.S. Department of Labor
Mine Safety and Health Administration



HAULAGE SAFETY



BEST PRACTICES

1. Provide and maintain adequate berms or bumper blocks at all dumping locations.
2. Examine dumping locations for hazards prior to commencing work.
3. Utilize a bulldozer with the "dump-short, push-over" method of spoiling material.
4. If dumping over a berm, back perpendicularly or at a slight angle, so that the driver side wheels contact the berm first.
5. Slope the dump area so that trucks must back up a slight grade.
6. Ensure that drivers are trained to recognize and avoid dumping hazards.
7. All personnel, who operate or ride in mobile equipment, should wear seat belts at all times the equipment is in motion.